

03500.013330.2

PATENT

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:		)	
YUTAKA MARUYAMA, ET AL.		:	Examiner: T.V. Nguyen
		;	Group Art Unit: 3729
Application No.: 10/700,852		)	
Filed: November 5, 2003		: )	
For:	METHOD FOR PRODUCING A STACKED PIEZOELECTRIC ELEMENT	) : )	May 24, 2006
U.S. Patent No. 6,951,048 B2		: )	Cersis
Issued: October 4, 2005		)	Certificate MAY 3 0 2006 Of Correction
Commi	issioner for Patents		or Correction
P.O. Bo	ox 1450		
Alexan	dria, VA 22313-1450		

### REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

05/25/2006 SZEWDIE1 00000151 6951048 01 FC:1811 109.00 OP Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Scott D. Malpede

Attorney for Patentees Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM\mm

DC\_MAIN 231223v1

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,951,048 B2

DATED

October 4, 2005

INVENTOR(S) :

YUTAKA MARUYAMA, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### [75] INVENTORS:

"Nobuyuki Kojima, Kanagawa-ken (JP);" should read --Nobuyuki Kojima, Yokohama (JP);-- and "Takahiro Yamakawa, Saitama-ken (JP)" should read --Takahiro Yamakawa, Konosu (JP)--.

#### COLUMN 2:

Line 35, "area a" should read --area  $\alpha$ --.

#### COLUMN 9:

Line 59, "23-2-23-9 are" should read --23-2 to 23-9 are--.

#### COLUMN 11:

Line 15, "junctions" should read --junctions of--.

DC\_MAIN 231221v1

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,951,048 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

MAY 3 U ZUUB

# UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO.

6,951,048 B2

**DATED** 

October 4, 2005

INVENTOR(S) :

YUTAKA MARUYAMA, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### [75] INVENTORS:

"Nobuyuki Kojima, Kanagawa-ken (JP);" should read -- Nobuyuki Kojima, Yokohama (JP); -- and "Takahiro Yamakawa, Saitama-ken (JP)" should read -- Takahiro Yamakawa, Konosu (JP)--.

#### COLUMN 2:

Line 35, "area a" should read --area  $\alpha$ --.

#### COLUMN 9:

Line 59, "23-2-23-9 are" should read --23-2 to 23-9 are--.

#### COLUMN 11:

Line 15, "junctions" should read --junctions of--.

DC MAIN 231221v1

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,951,048 B2

No. of add'l. copies @ 30¢ per page

